Knowledge Base Article #ETM634, Rev B

Release Notes for ETM® System v5.1 Update 3

Who Should Install This Software

ETM® System v5.1 Update 3 is recommended only for customers currently running v5.1 who are experiencing the issue described in this article. If you are experiencing an issue described in this article, contact SecureLogix Customer Support to obtain the update. It is a cumulative software update that includes all fixes and enhancements issued since Release 5.1, including the changes in v 5.1 Update 2.

This software update can only be installed on ETM System Software v5.1. If you are running a previous version of ETM software, please contact your Account Executive or SecureLogix Customer Support for updated software.

About This Document

This document contains important information about ETM® System v5.1 Update 3. The ETM System includes the ETM Communications Appliances, ETM Server software, and the ETM applications: the Performance Manager, the Voice Firewall, the Usage Manager, AAA Services for the Voice Firewall, the Voice IPS (Intrusion Prevention System), and the Call Recorder.

Changes in v5.1 Update 3

- 6124—Implemented support for ETSI DTMF Caller ID (ETS 300 659-1). DTMF caller ID is supported on UK analog lines that send a polarity reversal and the DTMF caller ID prior to the first ring.

IMPORTANT *Remote Clients must be upgraded before they are used to connect to the upgraded ETM Server.*

Note: *For a description of the changes in update 5.1 Update 2, see the SecureLogix Knowledge Base.*

Versions Installed in v5.1 Update 3

ETM Management Server and Client Software—5.1 build 18-2

ETM Appliance Software—5.1.14 (appliance upgrades only) and 5.1.16 (current appliance version)

Files Installed

The tables below list the files installed by the software update installer, depending the type of installation you choose.

Client Only	
Telewall.jar	slc-crypt.jar
slc-crypt.hmac	version.txt

Complete		
slc-crypt.hmac	ETM_1012_5.1.16.pkg	ETM_3000_5.1.16.pkg
slc-crypt.jar	ETM_1012_5.1.16_P2.pkg	ETM_3000_5.1.16_P2_bin.pkg
TeleWall.jar	ETM_1060_5.1.16.pkg	ETM_3000_5.1.16_P2_img.pkg
Version.txt	ETM_1060_5.1.16_P2.pkg	ETM_3070_5.1.14.0.pkg*
ETM_1010_5.1.14.0.pkg*	ETM_1090_5.1.16.pkg	ETM_3070_5.1.14.1.pkg*
ETM_1010_5.1.14.1.pkg*	ETM_3000_5.1.14.0.pkg*	ETM_3070_5.1.16.pkg
ETM_1010_5.1.14.pkg*	ETM_3000_5.1.14.1.pkg*	ETM_3070_5.1.16_P2_bin.pkg
ETM_1010_5.1.16.pkg	ETM_3000_5.1.14.pkg*	ETM_3070_5.1.16_P2_img.pkg

Complete with Call Recorder	
All of the files listed under **Complete**, plus the following appliance software packages:	
ETM_1012_5.1.16_REC.pkg	ETM_3000_5.1.14.1_REC.pkg*
ETM_1090_5.1.16_REC.pkg	ETM_3000_5.1.14_REC.pkg*
ETM_3000_5.1.14.0_REC.pkg*	ETM_3000_5.1.16_REC.pkg

The .14 packages included in the installater are the latest software packages for upgrading appliances from a version prior to v5.0. For instructions on upgrading from versions prior to v5.0, refer to the upgrade documentation in the SecureLogix Knowledge Base. Contact SecureLogix Customer Support for more information before using these packages.

Note: *Legacy ETM digital appliances and AAA appliances (1000, 1020, 1030, and 1040 models) do not support software updates past version 5.0.55 and will not have software updates available beyond that version.*

Last Update: 3/23/2006